RC8T4 Gearbox Upgrade Supplemnt #80951 / 80952 12 3 2024


:: RC8T4 T4e Manual - Page 5 - Step 2



There is an updated version of the gearbox.

It is idicated by the bump on the middle of the cap as shown here.

Do not run the older сар.



Step 1:

Add shims on the ring gear side to TIGHTEN gear mesh. Subtract shims on this side to LOOSEN gear mesh. NOTE:

Start 1x Thick 0.2mm

Step 2:

Add or subtract shims here to finalize diff side to side play once gear mesh is set from Step 1. Recommended diff "side-toside" clearance (gearbox assembly) 0.10 - 0.25mm.

Start with 1 x 0.1 mm. Note:

0.1 mm shim can be used for fine tuning of gear mesh

:: RC8T4 T4e Manual - Page 11 - Steps 1, 2



