

For Immediate Release: July 19, 2021

## New! RC10T6.2 Side Rails, hard



New for the RC10T6.1 and RC10T6.2 are "hard" material side rails. These side rails feature the added fan mount location, which has been made standard on the RC10T6.2. The hard material is stiffer than the standard material version.

UPC	Part No.	Description	MSRP	MAP	Available
784695711433	71143	RC10T6.2 Side Rails, hard	\$10.99	\$10.99	<a href="#">BUY NOW!</a>